



## PE REPAIRING PROCEDURE




1) Clean the damaged surface




2) Heat with a paint burner the edges of the damaged part till PE softening



3).Position a tip of a PE strip on the crack then heat it till softening.



4) Spread progressively the strip on the crack length.



5) Finish spreading with a cutter and scraping off the excess of PE.